

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Figure 1

TITLE: Mirror For Improved Visibility Of Danger
Zone Area On Right Side Of School Buses
INVENTOR: Gloria Buley
APPLICATION NO.: Not yet assigned,
CONF. NO. : DOCKET NO. 15328US01
ATTORNEY: RHS, PHONE: 312-775-8000




FIG 2

TITLE: Mirror For Improved Visibility Of Danger
Zone Area On Right Side Of School Buses
INVENTOR: Gloria Buley
APPLICATION NO.: Not yet assigned,
CONF. NO. : DOCKET NO. 15328US01
ATTORNEY: RHS, PHONE: 312-775-8000







Figure 5

TITLE: Mirror For Improved Visibility Of Danger
Zone Area On Right Side Of School Buses
INVENTOR: Gloria Buley
APPLICATION NO.: Not yet assigned,
CONF. NO. : DOCKET NO. 15328US01
ATTORNEY: RHS, PHONE: 312-775-8000